

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC 2000-000000-000341111145
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
01 REPORT SOURCE L 605000316712108380104849
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DURING NORMAL OPERATION WHILE PERFORMING A SURVEILLANCE TEST ON ESF FAN 2-HV-AES-1
03 A SUSPICIOUS ODOR WAS NOTED. THE FAN WAS REMOVED FROM SERVICE AND A COUPLING HALF
04 WAS FOUND LOOSE AND THE COUPLING HALVES DISENGAGED. FRICTION BETWEEN THE RUBBER
05 COUPLING FACES HAD CAUSED THE ODOR. THIS CONDITION IS NONCONSERVATIVE WITH RESPECT
06 TO T.S. 3.7.6. 2-HV-AES-2 REMAINED OPERABLE. ACTION REQUIREMENTS WERE MET.
07 PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

08

09 SYSTEM CODE SH 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE M E C F U N 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 18 19 20
17 LER-RO REPORT NUMBER 83 21 22 122 24 26 27 103 28 29 1 30 31 0 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
E 18 Z 19 Z 20 Z 21 00000 N 23 Y 24 A 25 W 26 8 27 7 28

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE CAUSE OF THE LOOSENING OF THE COUPLING HALF SET SCREWS IN THE SURE-FLEX SIZE
11 10 TYPE S COUPLING COULD NOT BE DETERMINED. THE COUPLING WAS REENGAGED AND THE
12 SCREWS SECURELY TIGHTENED. THE FAN WAS TESTED AND RETURNED TO SERVICE IN 5 HOURS
13 AND 7 MINUTES. COUPLINGS ON SIMILAR FANS IN BOTH UNITS HAVE BEEN INSPECTED.
14 NO DEFICIENCIES WERE NOTED.

15 FACILITY STATUS E 28 100 29 NA 30 METHOD OF DISCOVERY B 31 OPERATOR OBSERVATION 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

16 RELEASED OF RELEASE Z 33 Z 34 NA 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION 39 NA 40
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION 41 NA 42
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION 43 NA 44
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

20 PUBLICITY ISSUED N 44 DESCRIPTION 45 NA 46
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

8401130353 840104
PDR ADOCK 05000316
S PDR

NRC USE ONLY

NAME OF PREPARER ROBERT H. PIEHL

PHONE 616-465-5901