

3150-0011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE		COMP. SUBCODE	VALVE SUBCODE																	
0	9	S	G	11	X	12	Z	13	M	14	O	15	T	16	R	17	X	18	Z	19	Z	20		
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																
17	LER/RO REPORT NUMBER	8	3	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER								
X	18	D	19	Z	20	Z	21	0	0	0	0	0	0	N	23	N	24	X	25	U	0	0	0	5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The thermal overload trip of Fan S-36 was determined to be caused by the fan

1 1 motor current exceeding its nameplate rating of 10.5 amps. Immediate corrective

1 2 action was to restart Fan S-36 by resetting the thermal overload switch. Inves-

1 3 tigation revealed the need to rewind Fan S-36's motor. Fan S-35 has been

1 4 returned to service. Fan S-36's motor was removed and is currently being rewound.

FACILITY STATUS				% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	G	28	0	0	0	29	N/A	A	31	Operator Observation	

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 34 N/A

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURE NUMBER		TYPE	DESCRIPTION
1	7	000 (37) Z (38)	N/A

PERSONNEL INJURIES		(41)
NUMBER	DESCRIPTION	
1800	(40) N/A	

LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)

1 9 7 (42) N/A

IE22

2 0 N 44 N/A PDR ADOCK 05000275 PDR NRC USE ONLY

PHONE: (805) 541-7484

RECEIVED
MRC

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 799-2211 • TWX 910-372-6587

JAMES D. SHIFFER
MANAGER

DEPARTMENT OF NUCLEAR PLANT OPERATIONS
NUCLEAR POWER GENERATION

REGION VIAE

January 10, 1984

PGandE Letter No.: DCL-84-009

Mr. John B. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission, Region V
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368


Re: Docket No. 50-275, OL-DPR-76
Diablo Canyon Unit 1
Licensee Event Report 83-036/03L-0
Control Room Ventilation System

Dear Mr. Martin:

Pursuant to Section 6.9.1.13b of the Technical Specifications, Appendix A to the Diablo Canyon Unit 1 Operating License, the enclosed Licensee Event Report is submitted concerning the Control Room Ventilation System and the subsequent entering of the action statement of Technical Specification 3.7.5.1.

This event has in no way affected the public's health and safety.

Sincerely,


for James D. Shiffer

Enclosure

cc: G. W. Knighton

Director, Office of Management Information
and Program Control

Service List

IE-22
11