



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

DMB

December 22, 1983

Mr. James G. Keppler, Director
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: LaSalle County Station, Unit 2
10 CFR 50.55(e) Notification 83-05
Final Report, G.E. HMA Relays
NRC Docket No. 50-374

Reference (a): C. W. Schroeder letter to J. G. Keppler
dated September 1, 1983.

Dear Mr. Keppler:

Commonwealth Edison notified your office on August 5, 1983 of a reportable deficiency in accordance with 10CFR50.55(e) concerning potentially defective HMA relays manufactured by the General Electric Company.

The review of all Unit 2 safety related HMA relays was performed in two steps. At the time of our interim report (Reference (a)) a HMA list had been prepared and inspected per G.E.'s recommended procedure (G.E. FDI TEGX Rev. 0). Two relays were found to have insufficient armature clearance and have been adjusted. Further review of electrical drawings added several more panels providing a complete list of safety related HMA relays for LSCS Unit 2. The second review step involved inspecting the additional panels which did not turn up any defective relays. Now that all safety related HMA relays with the date codes in question have been inspected and repaired for LSCS Unit 2 we believe this issue is closed.

If there are any questions concerning this subject, please contact this office.

Very truly yours,

8401050413 831222
PDR ADOCK 05000374
S PDR

C. W. Schroeder 12/22/83

C. W. Schroeder
Nuclear Licensing Administrator

lm

7857N

DEC 27 1983
752210