

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER

VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

December 9, 1983


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Re: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
IE Bulletin 83-06

Dear Sir:

By letter dated November 18, 1983, Duke submitted a response to IE Bulletin 83-06 concerning non-conforming materials supplied by Tube-Line Corporation. Attached please find Supplement 1 to the initial response which contains information which was inadvertently omitted.

Very truly yours,



Hal B. Tucker

RLG/php

Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station

Mr. John F. Suermann
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8401050414 831209
PDR ADOCK 05000269
Q PDR

JEH
1/1

Duke Power Company
Oconee Nuclear Station
Response to IE Bulletin 83-06
Supplement 1

This supplement provides information which was inadvertently omitted from the initial response to IE Bulletin 83-06.

- a. Provide a list of the Tube-Line supplied materials and identify the systems in which the materials are installed.

Response

4 pcs, 8" x 4", Schedule 40, SA-234 WPB Reducing Tees
Presently located in warehouse tagged with QA Hold

9 pcs, 4" Schedule 40, SA-234 WPB Long Radius 90° ELLs

3 pcs. presently located in warehouse tagged with QA Hold
6 pcs. installed in non-safety applications

- b.

Response

Presently, final disposition of these items is still under evaluation. However, unless these items can be confirmed to be able to perform their intended service, they will not be used in a safety-related application.

- c. Not applicable