



DMB

Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

December 22, 1983

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42

Isolation Valve Failure of LLRT

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.1.C since it indicates an abnormal degradation in fuel cladding, reactor coolant pressure boundary, or primary containment.

David Musolf for

David Musolf
Manager - Nuclear Support Services

DMM/TAP/dab

c: Document Control Desk, NRC (1)
Resident Inspector, NRC
MPCA
Attn: J W Ferman

Attachment

DEC 30 1983
FE22/11