

ILLINOIS POWER COMPANY

U- 0680  
0982-L

500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525

Docket No 50-461

December 20, 1983

Mr. James G. Keppler  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Subject: IE Bulletin 83-07

Dear Mr. Keppler:

Illinois Power Company has completed a comprehensive review of vendors and their suppliers as a result of the subject bulletin. The following is provided in response to the list of actions required:

1. (a) The following Ray Miller, Inc. customers have furnished material for use at the Clinton Power Station (CPS) through the General Electric Company or Baldwin Associates:
  - (1) Permutit
  - (2) Richmond Engineering
  - (3) United Alloy Products
  - (4) Dresser Industries
  - (5) Midland Pipe & Supply
  - (6) Bethlehem Steel
  - (7) Irwin Steel (W. J. Wooley)
  - (8) Gould, Inc.
- (b) Based on research by General Electric and Baldwin Associates (BA), IP is confident that no Ray Miller, Inc. material was supplied through these companies for CPS.

8401050475 831220  
PDR ADOCK 05000461  
Q PDR

DEC 22 1983

IE//10

This conclusion is based on the following:

- (1) Permutit was an approved supplier to General Electric. Research by GE has determined that no Ray Miller, Inc. materials were supplied to CPS by Permutit.
- (2) Richmond Engineering was an approved supplier to both GE and BA. Both firms have received positive responses from Richmond Engineering indicating that no Ray Miller, Inc. material was supplied to CPS.
- (3) United Alloy Products was a GE approved supplier. United Alloy Products is no longer in business. The last GE order from United Alloy Products was delivered in 1975. The bulletin indicates that United Alloy placed one order with Ray Miller, Inc. on May 15, 1978. GE's order from United Alloy Products could not have contained this material.
- (4) Dresser Industries was an approved supplier to Baldwin Associates. Dresser has completed and returned a questionnaire indicating that no Ray Miller, Inc. material was supplied to CPS.
- (5) Midland Pipe and Supply has completed and returned a questionnaire stating that Ray Miller, Inc. was not on their Approved Suppliers List for safety-related orders.
- (6) Bethlehem Steel was only approved for supply for reinforcement steel by Baldwin Associates.
- (7) Irwin Steel was a material manufacturer that was purchased by W. J. Wooley Company, an approved BA supplier. W. J. Wooley has conducted an investigation and reported that no Ray Miller, Inc. material was supplied for CPS.


U-0680  
0982-L

Page 3

- (8) Gould, Inc. was only approved for supply of electrical components by Baldwin Associates.
- (c) Item (c) is not applicable based on the research conducted by GE and Baldwin Associates.
- (d) We have not identified any Ray Miller, Inc. materials installed or in-stock at CPS.
- 2. Item 2 is not applicable.
- 3. Item 3 is not applicable.
- 4. This letter constitutes our report on this subject.

Should you have any further questions on this issue, please let me know. I hereby affirm that the information in this letter is correct to the best of my knowledge.

Sincerely yours,

  
D. P. Hall  
Vice President

GEW/lt

cc: US NRC, Document Control Desk, Washington, D.C.  
G. A. Harrison, NRC Clinton Licensing Project Manager  
NRC Resident Office  
Illinois Department of Nuclear Safety