

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
C	B	E		C		P	I	P	E	X	X	E	Z				
9	10	11	12	12	13	13	14	14	15	15	16	16	17				
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
8	3	0	2	1	0	1	T	4									
21	22	23	24	25	26	27	28	29									
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
X	X	Z	Z	0	0	0	N	N	N	D	2	4	0				
18	19	20	21	22	23	24	25	26	27	28	29	30	31				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS (1) 5 (H) (28) % POWER (0) 0 (0) (29) OTHER STATUS (30) NA
 METHOD OF DISCOVERY (C) (31) Special Inspection of S.S. piping (32)
 ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (Z) (33) AMOUNT OF ACTIVITY (35) NA
 LOCATION OF RELEASE (36) NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	40
				NA	

8401050500 831213
PDR ADOCK 05000265

7 8 9 10 68 69 30

PUBLICATION ISSUED DESCRIPTION NA

2 0 N 44

1822

NRC USE ONLY

NAME OF PREPARER D Clark

PHONE 309-654-2241, ext 244

NRC USE ONLY



Commonwealth Edison

Quad Cities Nuclear Power Station
22710 206 Avenue North
Cordova, Illinois 61242
Telephone 309/654-2241

DMB

NJK-83-470

December 13, 1983

J. Keppler, Regional Administrator
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reference: Quad-Cities Nuclear Power Station
Docket Number 50-265, DPR-30, Unit Two
Appendix A, Section 6.6.B.1.c

Enclosed please find Reportable Occurrence Report Number RO 83-21/01T-4 for Quad-Cities Nuclear Power Station. Revision 4 of this occurrence was previously reported to Region III, Office of Inspection and Enforcement by telephone and by telecopy on December 14, 1983.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.1.c, an abnormal degradation discovered in the Reactor Coolant Pressure Boundary.

Respectfully,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

L. J. Kalivianakis for
N. J. Kalivianakis
Station Superintendent

NJK:DGC/bb

Enclosure

cc B. Rybak
A. Morrongiello
INPO Records Center

DEC 30 1983

FE2211