

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	R	A	N	0	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35											
LICENSEE CODE															LICENSE NUMBER										LICENSE TYPE										CAT 58				

CON'T

0	1	L	6	0	5	0	0	0	3	6	8	7	1	2	1	6	7	9	8	0	1	1	5	7	9	9								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35						
REPORT SOURCE					DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During Mode 3 operation, while performing normal surveillance testing,

0 3 2 CV-1039-2 failed to operate from the control room, rendering EFW pump

0 4 2 P7A feed to steam Generator 2E24B inoperable. Operability is required

0 5 for associated flowpath per T.S.3.7.1.2. LER's 50-368/78-09 & 02 also

0 6 involved the Emergency Feed after system. Reportable per T.S.6.9.1.9.(b)

0 7

0 8

0	9	W	B	11	E	12	A	13	R	E	L	A	14	S	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE	

17 LER/RO REPORT NUMBER 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 ACTION TAKEN 19 FUTURE ACTION 20 EFFECT ON PLANT 21 SHUTDOWN METHOD 22 HOURS 23 ATTACHMENT SUBMITTED 24 NPD-4 FORM SUB. 25 PRIME COMP. SUPPLIER 26 COMPONENT MANUFACTURER

19 A 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 N 25 E 26 2 9 9 27

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Cause of failure was located in solid state relay actuating 2 CV-1039-2 on

1 1 MSIS, sealing in a closed command. In the event of EFAS, the relay would

1 2 have been over-riden as the valve was inoperable with manual signals only.

1 3

1 4

1	5	B	28	0	0	0	29	NA	A	31	NA	32		
7	8	9	10	11	12	13	14	15	16	17	18	19		
FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		

1 6 Z 33 Z 34 NA 35 NA 36

1 7 0 0 0 37 Z 38 NA 39

1 8 0 0 0 40 NA 41

1 9 Z 42 NA 43

2 0 N 44 NA 45

2 1

2 2

2 3

2 4

2 5

2 6

2 7

2 8

2 9

3 0

3 1

3 2

3 3

3 4

3 5

3 6

3 7

3 8

3 9

4 0

4 1

4 2

4 3

4 4

4 5

4 6

4 7

4 8

4 9

5 0

NAME OF PREPARER Chris N. Shively

PHONE 501-968-2519

7901300070