

UPDATE

LICENSEE EVENT REPORT

Update 4/8 Ruiz

CONTROL BLOCK: 0232901

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 C 0 F S V 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 2 0 4 1 5
7 8 9 9 14 15 25 26 37 38 40 41 42 43 44 45 46 47 48

CON'T
01 REPORT SOURCE L 8 0 5 10 10 10 12 16 17 7 0 1 1 1 2 7 9 3 0 1 2 2 7 0 9
7 8 9 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During testing it was discovered that three of twelve helium circulator seal mal-
03 function differential pressure switches tripped outside the limits of LCO 4.4.1,
04 Table 4.4-3. Reportable per Technical Specifications AC 7.5.2(b)1 and AC 7.5.2(b)2.
05 No effect on public health or safety. Redundant system not available for one of the
06 circulators but was available for the other three circulators. Similar occurrence
07 Reportable Occurrence Report No. 77-47.

08 9 90

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
C B 11 E 12 E 13 I N S I R U 14 S 15 Z 16
17 LER NO REPORT NUMBER 7 8 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED APPROX FORMULA PRIME COMP SUPPLIER COMPONENT MANUFACTURER
X 18 X 19 Z 20 0 0 0 0 Y 23 N 24 N 25 B 26 27 28 29 30 31 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 ITT Barton Model 289 pressure differential switches failed to activate at trip point
11 due to dirt accumulation in switches. Trip settings being checked on a monthly
12 basis. Problem under investigation.
13
14

15 9 90

15 FACILITY STATUS 1 POWER 2 OTHER STATUS 30 METHOD OF DISCOVERY 31 DISCOVERY DESCRIPTION 32
E 28 0 6 2 29 N/A C 31 Operability Test
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 ACTIVITY CONTENT RELEASED OR RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 32 Z 34 N/A N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED DESCRIPTION 45
N 44 N/A
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

7901300112

NRC USE ONLY

NAME OF OPERATOR

J. W. Gahn

(303 785-2253)