

# NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

January 25, 1979

Mr J G Keppler, Director  
Office of Inspection & Enforcement  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr Keppler:


PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-306 License No. DPR-60

Setpoint Drift -  
Steam Flow Transmitter

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.(a) since the safety feature instrument setting was less conservative than allowed by technical specifications.

Yours very truly,

  
L/O Mayer, PE  
Manager of Nuclear Support Services

LOM/JAG/deh

cc: Director, IE, USNRC (30)  
Director, MIPC, USNRC (3)  
MPCA  
Attn: J W Ferman

REGULATORY DEPT FILE COPY

A002  
5/11

-over-

75-300160