

USAEC HQS GTW

TLX#179      #A8235(1756)C1-P38594C1550023PD 06/04/74 1748

ICS IPHVEIC MMW

1974 JUN 4 01 9 48

03231 TDVE MORRIS IL 117 06-04 215P COT

MRS J F O'LEARY

U.S. ATOMIC ENERGY COMM.  
TWX UNIT

DIRECTOR

DIRECTORATE OF LICENSING

50-249

US ATOMIC ENERGY COMMISSION

WUX

50-249

WASHINGTON DC 60137

SUBJECT DPR-25, DRESDEN NUCLEAR POWER STATION UNIT 3.  
THIS WILL CONFIRMATION CONVERSATION WITH F. MAURA OF YOUR  
OFFICE AT 1330 HOURS THIS DATE CONCERNING AN APPARENT  
FAILURE OF THE (D) MAIN STEAMLINE HIGH RADIATION MONITOR

RECOVERED DURING WEEKLY SURVEILLANCE TESTING. THE (D)  
MAIN STEAMLINE HIGH RADIATION MONITOR FAILED TO TRIP WHEN  
A SIMULATED HIGH RADIATION SIGNAL WAS INJECTED. AN  
INVESTIGATION IS CURRENTLY UNDERWAY TO DETERMINE IF IT IS  
A MONITOR FAILURE OR MERELY A FAILURE OF THE TEST CIRCUIT.  
ADDITIONAL DETAILS AND THE RESULTS OF THE INVESTIGATION  
WILL BE FORTHCOMING IN THE FORM OF A 10 DAY LETTER IN

ACCORDANCE WITH SECTION 6.6.8.1.A OF THE TECHNICAL SPECIFICATIONS.

B B STEPHENSON

SUPERINTENDANT

DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON COMPANY

NR #1

MORRIS ILLINOIS 60450

USAEC HQS GTW

815P

NO WSH

8009190826

COPY SENT REGION

4993