

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

April 13, 1984

BECO. #84-055

Domenic B. Vassallo, Chief
Operating Reactors Branch #2
Division of Licensing
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

License No. DPR-35
Docket No. 50-293

Re: I.E. Bulletin 80-11 - Additional Information

Dear Sir:

This letter provides additional information concerning the status of masonry walls at Pilgrim Station, as discussed on March 8, March 21, and April 4, 1984 with Mr. Paul Leech of your office.

During the performance of a recent plant modification, we became aware of a condition which caused us to question the completeness of our statement contained in our November 5, 1980 response to I.E. Bulletin 80-11 that "all masonry walls in Pilgrim Station have been identified, marked on drawings as to their location, and surveyed as of November 1, 1980." Accordingly, we performed additional engineering and plant reviews during February and March which are continuing. These reviews have identified a limited number of additional safety-related walls and a larger number of masonry blockouts located in reinforced concrete walls.

We are continuing an expeditious and complete review of these findings and will continue to keep you informed. A report will be submitted at the completion of this effort.

Very truly yours,

W D Harrington

William D. Harrington

WDH/mg

8404170370 840413
PDR ADOCK 05000293
Q PDR

IE11
10