

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	N J O C P 11	2	0 0 0 - 1 0 0 0 0 0 0 - 1 0 0	3	4 1 1 1 1 1	4	5
LICENSEE CODE		LICENSE NUMBER		LICENSE TYPE		DATE	
CON'T							
01	L 6	0 5 1 0 0 0 2 1 1 9	7	1 2 1 1 0 8 2	8	0 1 1 1 1 8 3	9
REPORT SOURCE		DOCKET NUMBER		EVENT DATE		REPORT DATE	
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)							
On Friday, Dec. 10, 1982 at 0227 hours the reactor mode switch was							
repositioned from shutdown to refuel. IRM channels 16 and 17 were out							
of service at this time. This is a violation of protective instrumenta-							
tion requirements (TS 3.1.1, Items A.9. & K.6) since the minimum re-							
quired number of operational IRM channels were not met with the reactor							
mode switch in the refuel position. At 1806 hours an administrative rod							
block was inserted ensuring that rod withdrawal could not occur.							
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE							
R B		A		A		Z Z Z Z Z Z	
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE	
8 2		0 6 0		0 3		L	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD	
H		Z		Z		Z	
HOURS		ATTACHMENT SUBMITTED		NPRD-3 FORM SUB		PRIME COMP. SUPPLIER	
0 0 0 0		Y		N		Z	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)							
The cause of this occurrence was positioning the reactor mode switch to							
refuel without the minimum number of IRM channels operable. All control							
rods were inserted and none were moved during the occurrence. An							
administrative rod block was inserted until sufficient IRM monitoring							
instrumentation could be returned to service.							
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY	
G		0 0 0		NA		A	
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		DISCOVERY DESCRIPTION	
Z		Z		NA		Operator Observation	
PERSONNEL EXPOSURES		TYPE		DESCRIPTION		LOCATION OF RELEASE	
0 0 0		0		NA		NA	
PERSONNEL INJURIES		NUMBER		DESCRIPTION			
0 0 0		0		NA			
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION			
Z		0		NA			
PUBLICITY ISSUED		DESCRIPTION				NRC USE ONLY	
N		NA					

NAME OF PREPARER Robert J. Murdock

PHONE. (609) 971-4891