

CONTROL BLOCK: 

					1
--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

C	A	S	O	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	--	---

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	6	1	7	1	2	0	9	8	2	8	0	1	0	8	8	3	9
60	61									68	69						74	75						80
DOCKET NUMBER											EVENT DATE							REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | With the plant in Mode 1, Diesel Generator 2G002 failed to regulate at 60 Hz due  
0 3 | to failure of the electrical governor and was declared inoperable. Since the  
0 4 | diesel generator could have operated on the mechanical governor had there been a  
0 5 | loss of off-site power, there was no impact on plant operation or the health and  
0 6 | safety of plant personnel or the public. (See also LER's 82-015 and 82-166).  
0 7 |  
0 8 |

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
		E	E	E		A		E	N	G	I	N	E	Z	Z
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
17		8	2	1	6	4	0	3	L		0				
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54
A	A	Z	Z					0	0	0	0	N	N	X	G

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Investigation revealed that the problem was attributable to the electrical governor.

1 1 Failure of the governor was caused by a burnt resistor in the power supply for the

1 2 control unit. The power supply was replaced. Additional corrective action will

1 3 include installation of a power supply of a different design not susceptible to this

1 4 type of failure.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	B	28	0	5	0	29	N/A	B	31	Surveillance Testing	32
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
1	6	Z	33	Z	34	N/A	35	N/A	36			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	37	Z	38	N/A				
PERSONNEL INJURIES		NUMBER		DESCRIPTION								
1	8	0	0	0	40			N/A				
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION								
1	9	Z	42			N/A						
PUBLICITY		ISSUED		DESCRIPTION								
2	0	N	44			8302010405 830108						
						PDR ADOCK 05000361						
						S	PDR					
								NRC USE ONLY				

NAME OF PREPARED

H.B. RAY HB Ray / N. Chandra

PHONE

714-492-7700