



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 5, 1984


W3K84-0812  
Q-3-A35.07.57

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

REFERENCE: LP&L letter W3K84-0326 dated February 15, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 57  
"Inadequate Instrumentation and Control Installations Turnover  
Documentation"  
Eight Interim Report



The above referenced letter indicated submittal of the Final Report to the USNRC on April 6, 1984.

At the present time, final review of corrective action documentation is scheduled to be completed in late May 1984. The Final Report will be submitted to the USNRC on June 15, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8404190251 840405  
PDR ADOCK 05000382  
S PDR

1/0 IE-27

Mr. John T. Collins  
April 5, 1984  
W3K84-0812  
Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814