

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

03 | A second HPSI pump was also available, it had completed all surveillances required to

04 demonstrate operability except the balanced flow test, which is to be done at the next

05 | refueling shutdown. The plant operated in accordance with TSAS 3.5.2.a for 9 hrs.

06 | Similar LER's: None

07 |

0 8 |

7	8	9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
---	---	---	----------------	---------------	------------------	----------------	------------------	------------------

0 9 S F 11 X 12 Z 13 P U M P X X 14 B 15 Z 16

7	8	9	10	11	12	13	18	19	20	
SEQUENTIAL						OCCURRENCE		REPORT		REVISION

LER/RO REPORT	EVENT YEAR	REPORT NO.	CODE	TYPE	NO.
(17)	8 2	10 5 2	0 3	1 1	0

[illegible][illegible]

33

X

 34

Z

 35

Z

 36

0	0	0	0
---	---	---	---

 37

Y

 38

Y

 39

N

 40

I	0	7	5
---	---	---	---

 41

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The C service water pump was shutdown to repair a leak. To maintain two service

water pumps powered from separate emergency buses, the swing bus, powering the B

1	1	Water pumps from the 1900s are being used, and being replaced by new pumps.	1
---	---	---	---

1 2 HPSI and service water pumps, was lined up to the Facility II emergency bus. The

Facility I emergency bus powered the A HPSI and service water pumps. The C service

1	3	Facility & Emergency has powered the A-101 and service water pump. The A-101 has
---	---	--

1 4 water pump was repaired and returned to service.

7	8	9		(30)	METHOD OF		(32)
FACILITY							

STATUS		% POWER		OTHER STATUS		DISCOVERY		DISCOVERY DESCRIPTION	
1	5	10	28	10	0	0	0	29	NA
								Operator Observation	

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80						
ACTIVITY CONTENT																																																																															

ACTIVITY	CONTENT	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
RELEASED	17	17	17
OF RELEASE	17	17	17

7 8 9 10 11 NA 44 45 8

[illegible]

1	7	0	0	0	(37)	Z	(38)	NA
---	---	---	---	---	------	---	------	----

7 8 9 11 12 13
PERSONNEL INJURIES
PROSECUTION (41)

NUMBER		DESCRIPTION	
1	8	0	0
0	0	0	40
		NA	

7 8 9 11 12

LOSS OF OR DAMAGE TO FACILITY

LOSS OF OR DAMAGE TO FACILITY		(4)
TYPE	DESCRIPTION	NA
17	(C)	

7 8 9 10 8303030324 830128 8

ISSUED (45) PDR ADOCK 05000336 NRC USE ONLY

[illegible]

NAME OF RESPONDENT Thomas P. Filburn PHONE (203) 447-1791 X 4424