

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Turkey Point Plant - Unit 3DOCKET NUMBER (2)
0 5 0 0 0 2 5 0 1 OF 0 1TITLE (4)
Breach of Fire BarriersEVENT DATE (5)
MONTH DAY YEAR
8 4 1984
LER NUMBER (6)
YEAR SEQUENTIAL NUMBER REVISION NUMBER
84 010 000
REPORT DATE (7)
MONTH DAY YEAR
4 1 7 8 4
OTHER FACILITIES INVOLVED (8)
FACILITY NAMES DOCKET NUMBER(S)
Turkey Point - Unit 4 0 5 0 0 0 2 5 1
N/A 0 5 0 0 0OPERATING MODE (9)
POWER LEVEL (10)
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)
20.402(b) 20.406(c) 50.73(a)(2)(iv) 73.71(b)
20.406(a)(1)(i) 50.73(a)(2)(v) 73.71(c)
20.406(a)(1)(ii) 50.73(a)(2)(vi) X OTHER (Specify in Abstract below and in Text, NRC Form 366A)
73.406(a)(1)(iii) 50.73(a)(2)(vii)(A) Special Report
20.406(a)(1)(iv) 50.73(a)(2)(vii)(B)
20.406(a)(1)(v) 50.73(a)(2)(viii)LICENSEE CONTACT FOR THIS LER (12)
NAME TELEPHONE NUMBER
Jesus Arias, Jr., Regulation and Compliance Lead Engineer 3 0 5 2 4 5 - 2 9 1 0COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)
CAUSE SYSTEM COMPONENT MANUFACTURER REPORTABLE TO NRC
CAUSE SYSTEM COMPONENT MANUFACTURER REPORTABLE TO NRCSUPPLEMENTAL REPORT EXPECTED (14)
YES (If yes, complete EXPECTED SUBMISSION DATE) NO
EXPECTED SUBMISSION DATE (15)
MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

As we reported on June 16, 1983 (L-83-364) and October 13, 1983 (L-83-519), many modifications have necessitated a number of fire barriers to be breached. In compliance with Technical Specifications, an hourly fire watch has been established.

Appendix R modifications are currently underway which include establishing specific fire area boundaries separated by rated fire barriers. All penetrations in a fire area boundary will be sealed in accordance with our Appendix R commitments, and will be included as part of the Appendix R backfit schedules. The hourly fire watch will continue to monitor these areas in accordance with Technical Specifications.



April 17, 1984
PNS-LI-84-131

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

Re: Special Report 84-10
Turkey Point Unit 3
Breach of Fire Barriers

The attached Special Report is being submitted pursuant to the requirements of 10 CFR to close out previous special reports. Because these barriers will be followed and addressed as part of the Appendix R modifications, we no longer plan to track them as special report items.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. Williams, Jr.", with a stylized flourish at the end.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: J. P. O'Reilly, Region II, USNRC
Harold F. Reis, Esquire
File 933.1

IEER
1/1