



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003

50-247

September 6, 1973

Re: Indian Point Unit No. 2
Facility Operating
License DPR-26

Mr. John F. O'Leary, Director
Directorate of Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20545



Dear Mr. O'Leary:

The following report of Abnormal Occurrence No. 3-2-11 is provided pursuant to the requirements of Section 6.12.2(a) of the Technical Specifications to Facility Operating License No. DPR-26.

On August 22, 1973, it is discovered that the instrument setting of one of the four channels of the low steam line pressure controllers in the high steam flow safety circuit was below that required by Table 3-1, No. 5. The setting was found to be 577 psig rather than the required 600 psig or greater. The anomaly was identified during the performance of Periodic Surveillance Test PT-M11, "Steam Line Pressure Analog Channel Functional Test". Unit No. 2 was operating at approximately 49% power at the time.

The discrepancy is believed to have resulted from instrument drift. To correct the situation, the channel was recalibrated and retested satisfactorily.

There are no safety implications associated with this occurrence since the three remaining channels in the low steam line pressure circuit would have produced the required protective action. The logic involved with this circuit requires actuation if two of four controllers sense low pressure.

8304050190 730906
PDR ADOCK 0500247
S PDR

6881

COPY SENT REGION

Mr. John F. O'Leary

- 2 -

September 6, 1973

The Station Nuclear Safety Committee and the Chairman of the Company's Nuclear Facilities Safety Committee have reviewed the above described occurrence and have approved the corrective action taken.

Warren R. Cobean Jr.

Warren R. Cobean, Jr.
Manager - Nuclear Power
Generation Department

TML/mo

cc/ Mr. James P. O'Reilly
Regulatory Operations, U.S.A.E.C.

MEMO ROUTE SLIP		See me about this.	For concurrence	For action.
Form AEC-93 (Rev. May 14, 1947) AECM 3		Note and return.	For signature.	For information.
TO (Name and unit)	INITIALS	REMARKS		
RO Chief, Field Support & Enforcement Branch, HQ	<i>[Signature]</i>	CONSOLIDATED EDISON COMPANY		
RO:HQ (5)		ABNORMAL OCCURRENCE		
DR Central Files				
TO (Name and unit)	INITIALS	REMARKS		
Central Mail & Files Regulatory Standards Regional Directors, RO (4)	(3)	The attached abnormal occurrence letter		
Directorate of	DATE	is forwarded for information. Distribution		
		will be made by this office to the PDR,		
TO (Name and unit)	INITIALS	REMARKS		
Licensing (13)		Local PDR, NSIC, DTIE, and State representatives		
	DATE	after review by the licensee for		
		proprietary information.		
FROM (Name and unit)	REMARKS			
<i>[Signature]</i>				
E. J. Brunner				
Region I				
PHONE NO.	DATE			
X 264	8/28/73			

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO : 1971 O - 445-460