



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

August 23, 1973
Indian Point Station

Re: Facility Operating
License DPR-26

Mr. James P. O'Reilly, Director
Regulatory Operations, Region 1
U.S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, we wish to inform you of an Abnormal Occurrence (A.O. 3-2-11) which was identified on August 22, 1973.

Periodic Surveillance Test PT-M11, "Steam Line Pressure Analog Channel Functional Test" was performed during power operation at approximately 49% power. The instrument setting for one channel of the low steam line pressure controllers in the high steam flow safety circuit was found to be below that required by Table 3-1, No. 5 (577 versus 600 psig). The remaining three channels were found to be operating correctly. The channel was recalibrated and retested satisfactorily.

Safety implications of this occurrence are considered to be slight since the remaining three channels of the 2 out of 4 actuation logic were set correctly and would have functioned if required.

Mr. Fasano of your office was notified of this occurrence by telephone on August 22, 1973.

Very truly yours,

Warren R. Cobean
Warren R. Cobean, Jr.
Manager, Nuclear Power
Generation Department

8304050196 730906
PDR ADOCK 05000247
S PDR

MFS:daf

Copy To: Mr. John F. O'Leary
Directorate of Licensing

50-347
216