

LICENSEE EVENT REPORT

CONTROL BLOCK

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: NYREG 1 LICENSE NUMBER: 00-000000-00 LICENSE TYPE: 41111 EVENT TYPE: 03

CONT: MI REPORT SOURCE: 050-0244 DOCKET NUMBER: 050-0244 EVENT DATE: 041875 REPORT DATE: 050875

EVENT DESCRIPTION

02 During routine operation a small leak was found on a letdown line drain line reducer
03 weld. The leak was repaired per the approved L-108 Emergency Maintenance
04 Procedure. PORC reviewed the event and corrective action taken and determined no
05 further corrective action was necessary. (Unusual Event 50-244/75-02)
06

SYSTEM CODE: CG CAUSE CODE: A COMPONENT CODE: PIPEXX PRIME COMPONENT SUPPLIER: O COMPONENT MANUFACTURER: Z999 VIOLATION: N

CAUSE DESCRIPTION

08 The weld, performed during construction in a relatively inaccessible location, was
09 applied such that there was a weld arc start on top of a stop leaving an area of incom-
10 plete fusion. This resulted in a weak point in the weld (Cont'd. in Additional Factors)

FACILITY STATUS: D % POWER: 000 OTHER STATUS: NA METHOD OF DISCOVERY: B DISCOVERY DESCRIPTION: routine shutdown operations
 FORM OF ACTIVITY RELEASED: Z CONTENT OF RELEASE: Z AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 000 TYPE: Z DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 000 DESCRIPTION: NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z DESCRIPTION: NA

PUBLICITY

17 NA

8304050606 750508
 PDR ADOCK 05000244
 S PDR

ADDITIONAL FACTORS

18 (Cause Description cont'd.) ultimately leading to the development of the leak.
19

NAME: James W. Witte

PHONE: 716-546-2700

Ext. 291-214

GPO 881-667



NEW
YORK
STATE

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE TEL. 546 2700

May 8, 1975

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Unusual Event 75-02, Small leak at letdown line drain weld.
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.6.2b, the attached report of Unusual Event 75-02 is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.

Attachment

cc: Mr. Donald F. Knuth (30)

5551