



Telegram

NK3639(2127)(1-058217A184)PD 07/03/73 2124

ICS IPMDONC NYK

03085 FR DC NEWYORK NY 228 07-03 508P EDT

PMS JAMES P OREILLY, DIRECTOR REGULATORY OPERATIONS

REGION 1 US ATOMIC ENERGY COMMISSION (DELIVER)

970 BROAD ST NEWARK NJ 07102

DEAR MR O'REILLY/

IN ACCORDANCE WITH THE REQUIREMENTS OF TECHNICAL SPECIFICATION 6.6.1.B, THE FOLLOWING ABNORMAL OCCURRENCE REPORT (A.O. 3-2-9) IS PROVIDED/ DURING THE PERFORMANCE OF PERIODIC TEST AND CALIBRATION PROCEDURE PTM-12 ON JULY 2, 1973, IT WAS DISCOVERED THAT THE FIRST STAGE TURBINE PRESSURE SETTING WAS SLIGHTLY IN EXCESS OF THE LIMIT DEFINED BY FACILITY TECHNICAL SPECIFICATION 2.3.2.A.2. INSTEAD OF THE TRIP BECOMING UNBLOCKED AT THE PRESCRIBED 10/ OF FULL POWER, MAXIMUM, ONE OF THE TWO CHANNELS WAS

7-1201 (RS-69)


FOUND TO BE SET AT 10.3 / ADDITIONALLY, THE PERIODIC TEST REVEALED THAT ONE OF EIGHT SAFETY INJECTION STEAM FLOW BI-STABLES WAS SET 0.3/ HIGHER THAN THAT PRESCRIBED IN TABLE 3.1 OF THE TECHNICAL SPECIFICATIONS. THE PROPER SETTINGS FOR THESE TWO DEVICES WERE ESTABLISHED DURING THE COURSE OF THE CALIBRATION CHECK.

AN INVESTIGATION AS TO THE CAUSE OF THE SETTING DEVIATIONS IS PRESENTLY BEING CONDUCTED. THE RESULTS OF THE INVESTIGATION, AND ANY MEASURES TAKEN TO PREVENT RECURRENCE, WILL BE REPORTED IN A LETTER PROVIDED WITHIN TEN (10) DAYS AS REQUIRED BY THE FACILITY LICENSE. IN ACCORDANCE WITH THE REQUIREMENTS OF TECHNICAL SPECIFICATION 6.2, NOTIFICATION TO THE CHAIRMAN OF THE NUCLEAR

7-1201 (RS-69)

8304060046 730703
PDR ADOCK 05000247
S PDR

50-247
Trifling



Telegram

FACILITIES SAFETY COMMITTEE HAS TAKEN PLACE. MR C OBERG OF
THE U.S. ATOMIC ENERGY COMMISSION, REGION 1, REGULATORY
OPERATIONS, WAS ALSO NOTIFIED BY TELEPHONE, OF THE
OCCURRENCE BY MR JOHN M MAKEPEACE, CHIEF ENGINEER OF
UNIT NO 2, ON JULY 2, 1973

COM EDISON NYC

MEMO ROUTE SLIP Form AEC-93 (Rev. May 14, 1947) AECM 0240		See me about this. Note and return.	For concurr. For signature.	For action. For information.
TO (Name and unit)	INITIALS	REMARKS		
✓ H. D. Thornburg, Chief FS&EB, RO <i>[Signature]</i>	DATE	CONSOLIDATED EDISON COMPANY		
		DOCKET NO. 50-247		
		ABNORMAL OCCURRENCE: TWX DATED 6/8/73		
TO (Name and unit)	INITIALS	REMARKS		
cc: RO:HQ (5) DR Central Files RO Files Reg. Standards (3)	DATE	The attached report from the subject licensee is		
		forwarded in accordance with RO Manual Chapter 1000.		
		The action taken by the licensee is considered		
TO (Name and unit)	INITIALS	REMARKS		
Dir. of Licensing (13)	DATE	appropriate. An RO inspector is presently at the		
		site. Copies of the report have been forwarded		
		to the PDR, Local PDR, NSIC, DTIE and State		
FROM (Name and unit)	REMARKS			
for <i>Rd. Heil</i> E. J. Brunner, RO:I	representatives. The licensee will submit a 10			
	day written report to Licensing			
PHONE NO.	DATE			
	6/11/73			

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO : 1971 O - 445-469