



western union

Telegram

NKA57R(2005)(1-057052A159)PD 06/02/73 2002

ICS IPMDONC NYK

0313R FR DC NEWYORK NY 185 06-02 618P EDT

PMS JAMES P OREILLY DIR

REGULATORY OPERATIONS REGION I

US ATOMIC ENERGY COMMISSION

970 BROAD ST

NEWARK NJ 07102

RE: INDIAN POINT UNIT #2 -FACILITY OPERATING

LICENSE DPR-26

IN ACCORDANCE WITH THE REQUIREMENTS OF TECHNICAL SPECIFICATION

6.6.1.B,

WE WISH TO INFORM YOU OF AN ABNORMAL OCCURRENCE,

(A.O. 3-2-8)

WHICH TOOK PLCE ON JUNE 7 1973.

BF-1201 (RS-69)



western union

Telegram

DURING THE COURSE OF PERFORMING PERIODIC TESTS AND CALBBRATION
CHECKS RELATING TO REACTOR COOLANT FLOW AS REQUIRED BY THE
FACLLITY TECHNICAL SPECIFICICATIONS,

IT WAS DETERMINED THAT THE FLOW TRIP SETTINGS WERE SLIGHTLY
BELOW THOSE SPECIFIED IN SPECIFICATION 2.3.1.

AT THE TIME OF THE OCCURENCE, THE REACTOR WAS CRITICAL AT ZERO P
OWER FOR ZERO POWER PHYSICS
TESTING.

IN ACCORDANCE WITH THE REQUIREMENTS OF TECHNICAL SPECIFICATTION
6.2, NOTIFICATION OF THE CHAIRMAN OF THE NUCLEAR FACILITIES
AFETY COMMITTEE HAS TAKEN PLACE.

MR A FASANO OF YOUR OFFICE WAS ALSO NOTIFIED BY TELEPHONE
ON JUNE 8 1973 OF THE OCCURENCE BY MR JOHN M MAKEPEACE,
CHIEF ENGINEER, UNIT NO 2

8304060053 730608
PDR ADDCK 05000247
PDR



Telegram

WE ARE CURRENTLY INVESTIGATING THE CAUSE OF THE OCCURRENCE
AND THE RESULTS OF OUR INVESTIGATION AND CORRECTIVE ACTION
TAKEN WILL BE SUBMITTED IN THE REQUIRED TEN DAY REPORT
TO THE DIRECTOR OF LICENSING

WILLIAM E CALDWELL-
CON EDISON CO
4 IRVING PLACE
NY NY 10003
TELEX NBR 12 7339