



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14647



TELEPHONE  
AREA CODE 716 546-2700  
Ginna Station  
January 9, 1975

Mr. James P. O'Reilly, Director  
Directorate of Regulatory Operations  
Region I  
U. S. A. E. C.  
631 Park Avenue  
King of Prussia, Pa. 19406

Subject: Abnormal Occurrence #75-1  
Failure of the Steam Driven Auxiliary Feedwater  
Pump to respond properly during surveillance  
test, Docket No. 50-244

Dear Mr. O'Reilly:

This is to confirm my phone call to Mr. Walter Baunack today to report  
Abnormal Occurrence #75-1 at Ginna Station.

While conducting the monthly PT-16, (Auxiliary Feedwater Flow) surveillance  
test on January 8, 1975, the steam driven auxiliary feedwater pump tripped out  
after running for approximately 15 seconds. The pump was started two  
more times, and each time it again tripped out after 15 seconds. The low  
lube oil pressure trip setpoint was adjusted and then the pump was started  
again. This time the pump remained in operation and the PT-16 surveillance  
test was completed with no further problems.

Very truly yours,

*Charles E. Platt*

Charles E. Platt  
Superintendent

CEP:bg

cc: Mr. J. F. O'Leary, AEC  
Mr. L. D. White, Jr., RG&E  
Mr. G. J. Swarthout, RG&E

8304060074 750117  
PDR ADDCK 03000244  
S PDR