

William F. Caldwell, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-5181

October 11, 1972

Re Indian Point Unit No. 2
AEC Docket No. 50-247


Mr. Frank E. Kreusi, Director
Directorate of Regulatory Operations
U.S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Kreusi

On September 12, 1972 Consolidated Edison notified the Commission by telephone that a Steam Generator nozzle debris plug assembly had been inadvertently left in place during a hydrostatic test of the Reactor Coolant System.

Enclosed herewith is a report entitled "Investigation and Consequences of a Steam Generator Nozzle Debris Plug Assembly Being Inadvertently Left In-Place During Operation of the Reactor Coolant System" dated October 11, 1972 for the above-referenced plant.

Very truly yours



enc
cw

Peter Zarakas
Acting Vice President

Copy to James P. O'Reilly, Director
Regulatory Operations
Region 1
U. S. Atomic Energy Commission
970 Broad Street
Newark, New Jersey 07102

8304060231 721110
PDR ADOCK 05000247
S PDR

50-247
inquiry

2 1443