




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 12, 1984

W3K84-0843
Q-3-A35.07.90



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L Letter W3K84-0325 dated February 15, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 90
"Electrical Conduit Overstressed"
Third Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on April 13, 1984.

At the present time, the results of independent testing is being evaluated for acceptability and is scheduled to be completed in early May 1984. The Final Report will be submitted to the USNRC on May 25, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8404260192 840412
PDR ADOCK 05000382
S PDR

IE-27 1/0

Mr. John T. Collins
April 12, 1984
W3K84-0843
Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814