

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 N Y N M P 1	LICENSE NUMBER 	LICENSE TYPE 4 1 1 1 1 1	EVENT TYPE 0 4
CATEGORY 01 CONT - -	REPORT TYPE T	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 2 0
EVENT DATE 1 2 x x 7 6	REPORT DATE 0 5 1 8 7 7		

EVENT DESCRIPTION

02 During a review of chemical discharge records for December 1976, it was found that the sodium valve for liquid effluents was 1.59 ppm vs a limit of 1.5 ppm. (ETS 2.3-1)

04 Pump out rate exceeded allowable for concentration in the make-up demineralizer waste tank. Review of records not made until May 1977.

05 LER 76-45

SYSTEM CODE 07 W C	CAUSE CODE A	COMPONENT CODE Z Z Z Z Z Z	PRIME COMPONENT SUPPLIER Z	COMPONENT MANUFACTURER Z X X X	VIOLATION N
---	---	---	---	---	--

CAUSE DESCRIPTION

08 The surveillance procedure was revised to assure a more timely check on concentration of discharges which have been made. A station modification to provide discharge throttling capability will prevent recurrence.

FACILITY STATUS 11 E	% POWER 0 9 7	OTHER STATUS NA	METHOD OF DISCOVERY B	DISCOVERY DESCRIPTION Routine surveillance
FORM OF ACTIVITY RELEASED 12 Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA	

PERSONNEL EXPOSURES

NUMBER 13 0 0 0	TYPE Z	DESCRIPTION NA
--	---	---

PERSONNEL INJURIES

NUMBER 14 0 0 0	DESCRIPTION NA
--	---

~~CONSEQUENCES PROBABLE~~

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z	DESCRIPTION NA
--	---

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

8304060402 770518
PDR ADOCK 05000220
S PDR

19 NA