


TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201

BILLY R. CLEMENTS
VICE PRESIDENT, NUCLEAR OPERATIONS

April 17, 1984
TXX-4154



Mr. E.H. Johnson, Chief
Reactor Project Branch 1
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

COMANCHE PEAK STEAM ELECTRIC STATION
CABLE TRAY SUPPORT COLUMN
QA FILE: CP-84-01, SDAR-125
FILE NO.: 10110

Dear Mr. Johnson:

On January 11, 1984 we verbally informed your Mr. R.G. Taylor of a deficiency regarding laminations and delaminations in a cable tray support column in the cable spread room.

We have completed our investigation and concluded that the matter is not reportable under 10CFR50.55(e). Records supporting this determination are available for your Inspector's review at the CPSES site.

Very truly yours

BRC:tlg

cc: NRC Region IV - (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8404260218 840417
PDR ADOCK 05000445
S PDR

13-27

1/0