

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

1                          6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	I						-								4	1	1	1	1	0	4
7	8	9					14	15									25		26				30	31	32	
CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE										
01	CON'T	-	-	T	L	0	5	0	-	0	2	2	0	1	0	1	2	7	6	1	0	1	5	7	6	
7	8	57	58	59	60	61							68	69					74	75					80	

EVENT DESCRIPTION	DATE	TIME	LOCATION	STATUS
...	...	...	...	...

02	Lake Surveillance Program. Benthos collections are required bimonthly. The August	80
03	1976 samples were not collected until 9/4/76. This is in excess of the +25% time	80
04	variation allowed in Sect. 1.16 of the Safety Technical Specifications. LER 76-35	80
05		80
06		80

		SYSTEM CODE		CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION	
[0]	[7]	[Z]	[Z]	[F]		[Z]	[Z]	[Z]	[Z]	[Z]	[Z]	[Z]		[Z]	[9]	[9]	[9]	-
7	8	9	10	11		12					17	43		44			47	48

## CAUSE DESCRIPTION

08 Contractor divers could not be used for the August collections due to recent OSHA  
7 8 9 regulations imposed on professional divers. Availability of a certified diver was 80  
09  
/ 8 9 such that collection was delayed until September 4, 1976. 80  
10  
7 8 9

11	7	8	FACILITY STATUS	9	% POWER	10	11	12	13	OTHER STATUS	44	METHOD OF DISCOVERY	45	46	DISCOVERY DESCRIPTION	80
										N/A			a			
12	7	8	FORM OF ACTIVITY RELEASED	9	CONTENT OF RELEASE	10	11	12	13	AMOUNT OF ACTIVITY	44		45	46	LOCATION OF RELEASE	80
										N/A				N/A		

## PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION	
1	3	0	0	0	Z	N/A
7	8	9	11	12	13	

## PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	N/A
7	8	9	11	12

QX888 CONSEQUENCES probable.

15	None
7 8 9	

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	6	7	N/A

## PUBLICITY

17 N/A PDR ADUCK 05000220  
789 S PDR

### ADDITIONAL FACTORS

10 Contractor is Lawler, Matusky, and Skelly Eng., Oswego, New York.

7 0 0