

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

  
1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE		
01	N	Y	N	M	P	1						-								4	1	1	1	1		0	3
7	8	9				14				15								25		26				30		31	32

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE							
01		M	1	L	L	0	5	0	-	0	2	2	0	0	4	2	3	7	6	0	5	2	1	7	6
7	8	57	58	59	60	61							68	69				74		75					80

[illegible]

02	During surveillance testing 02-13B a switch used for turbine auticipatory trip bypass	80
03	reactor scram was found to actuate at 364 psig rather than the required 355 + 5 psig.	80
04	Plant was operating above point thus required action would occur if required.	80
05		80
06		80
	RO 76-19	

SYSTEM CODE      CAUSE CODE      COMPONENT CODE      PRIME COMPONENT SUPPLIER      COMPONENT MANUFACTURER      VIOLATION

07    I    A    E    I    N    S    T    I    R    U    N    B    O    7    0    -

7 8 9 10      11      12      17      43      44      47      48

## CAUSE DESCRIPTION

08	Setpoint drift switch was recalibrated and placed back in service.	
09		50
10		80

11	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		80
7 8	C		0 6 0				b				
	9		10 12		13		44 45		46		80
FORM OF ACTIVITY RELEASED											
12	CONTENT OF RELEASE		AMOUNT OF ACTIVITY						LOCATION OF RELEASE		
7 8	Z		Z		N/A						
	9		10 11		44		45				

## PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	2	N/A

## PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	N/A

OFFSITE CONSEQUENCES probable

15	NONE
7 8 9	

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	3		N/A

## PUBLICITY

17	NONE	PDR ADDUCK 030000Z PDR
7 8 9		

### ADDITIONAL FACTORS

13 No hazard to plant or general public.

19 |

NIAGARA MOHAWK POWER CORPORATION

NIAGARA ~~221~~ MOHAWK

300 ERIE BOULEVARD, WEST  
SYRACUSE, N. Y. 13202

May 25, 1976

Mr. James P. O'Reilly  
Directorate of Regulatory Operations  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, Pa. 29406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

Enclosed please find LER Reports (76-19, 76-20, & 76-21) for  
Nine Mile Point Unit 1. These reports are in the acceptable format  
as required and as a point of clarification and due to the previously  
submitted type T reports on fish impingement, the numbering does not  
follow in chronological order. This system is being changed to pre-  
vent this problem in the future.

Very truly yours,

Original Signed by R.R. Schneider


R.R. Schneider  
Vice President  
Electric Operations

TJD/aih

Enc. 3 copies

CC: K.R. Goller (30 copies)



COPY SENT REGION 

5419