



Telegram

314P EST MAY 29 72 DEB036

SSG061 DE CPA039 MN PDF TDCP CORDOVA ILL

EDWARD JORDEN

REGION 3 COMPLIANCE UNITED STATES ATOMIC ENERGY COMMISSION
799 ROOSEVELT RD GLEN ELIYN ILL 60137

REFERENCE QUAD CITIES NUCLEAR POWER STATION UNIT 2DPR-30 APPENDIX

A SECTION 1.A.5 6.6.A.3 AND 6.6.B.3: AT 130AM ON MAY 29, 1972
THE UNIT 2 TORUS SUCTION HEADER (2-1501-24 INCH) AT QUAD CITIES
NUCLEAP POWER STATION WAS DISCOVERED TO HAVE HANGAR DAMAGE
AND WAS DISPLACED FROM ITS NORMAL POSITION. FOUR HANGAR BOLTS
HAD FAILED ON THE TORUS SUCTION HEADER, THESE HANGARS SUPPORTED
APPROXIMATELY A 90 DEGREE SECTOR OF THE TORUS. THE MAXIMUM
DOWNWARD DISPLACEMENT OF THE TORUS SUCTION HEADDR WAS 6 INCHES.
THE REACTOR WAS SHUT DOWN IMMEDIATELY AND WILL REMAIN SHUT
DOWN UNTIL THE CAUSE OF FAILURE IS DETERMINED AND REPAIRED
AND/OR MODIFICATION WORK ON THE TORUS SUCTION HEADER HANGARS

SF-1201 (R5-69)

western union

Telegram

IS COMPLETE

B STEPHENSON QUAD CITIES NUCLEAR POWER STATION CORDOVA ILLINOIS

2DPR-30 1.A.5 6.6.A.3 6.6.B.3 130AM 29 1972 2 (2-1501-24 906
(302).

8304070014 721127
PDR ADOCK 05000265
S PDR

SF-1201 (R5-69)