

LER 77-01/3L  
LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 N Y R E G 1 14  
 LICENSE NUMBER: 00-000000-00 25  
 LICENSE TYPE: 41111 30  
 EVENT TYPE: 03 31 32  
 CATEGORY: 01 CON'T 57 58  
 REPORT TYPE: L 59  
 REPORT SOURCE: L 60  
 DOCKET NUMBER: 050-0244 68  
 EVENT DATE: 010377 69 74  
 REPORT DATE: 012777 75 80

EVENT DESCRIPTION

02 During testing C SI pump failed to start manually from Bus 14 breaker on the first  
 03 attempt. Control switch was reset and pump started on next three attempts. It also  
 04 started successfully from bus 16 breaker. This incident is similar to 7 events  
 05 involving bus 16. (Reportable Occurrence 77-01, 30-day).  
 06

SYSTEM CODE: 07 S F 10  
 CAUSE CODE: E 11  
 COMPONENT CODE: C K T B R K 12 17  
 PRIME COMPONENT SUPPLIER: N 43  
 COMPONENT MANUFACTURER: W 1 2 0 44 47  
 VIOLATION: N 48

CAUSE DESCRIPTION

08 Complete inspection of circuit breaker and all circuitry in close circuit was made. The  
 09 only problem found was a weak spring in a secondary contact assembly which could  
 10 have caused intermittent faulty operation. Circuit (cont'd. under Additional Factors)

FACILITY STATUS: E 9  
 % POWER: 100 10 12 13  
 OTHER STATUS: NA 44  
 METHOD OF DISCOVERY: b 45  
 DISCOVERY DESCRIPTION: NA 46  
 FORM OF ACTIVITY RELEASED: Z 9  
 CONTENT OF RELEASE: Z 10  
 AMOUNT OF ACTIVITY: NA 44  
 LOCATION OF RELEASE: NA 45

PERSONNEL EXPOSURES

13 NUMBER: 000 11  
 TYPE: Z 12  
 DESCRIPTION: NA 13

PERSONNEL INJURIES

14 NUMBER: 000 11  
 DESCRIPTION: NA 12

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z 10  
 DESCRIPTION: NA

PUBLICITY

17 NA  
 8304070038 770127  
 PDR ADOCK 05000244  
 S PDR

ADDITIONAL FACTORS

18 (cont'd. from Cause Description) breaker is Westinghouse Model DB-50, 600V A.C.  
 19 Contact assembly was replaced. Pump will be started weekly with bus 14 breaker until next scheduled monthly surveillance test.

NAME: J. Noon PHONE: 716-546-2700, ext. 291-215

IE FILE COPY



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

January 27, 1977



Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 77-01 (30-day report), Bus 14 circuit  
breaker for "C" Safety Injection Pump  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.b, the attached report of Reportable Occurrence 77-01, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

*L. D. White, Jr.*  
L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)  
Mr. William G. McDonald (3)

~~REGION~~ I

1103