



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

May 25, 1976

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Supplemental Report on Reportable Occurrence 76-12, 30-day
report, dated April 23, 1976
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:


On April 23, 1976 we submitted Reportable Occurrence 76-12, 30-day report, Containment Personnel Airlock Handwheel Shaft Seal Excessive Leakage During Testing. In that report the statement was made that action to prevent a recurrence of that event was being investigated.

This is to inform you that the corrective action planned is to place keepers on the packing gland nuts to prevent them from rotating with the shaft, precluding their loosening and permitting leakage through the packing. These keepers will be installed at a future plant outage when the door assemblies can be dismantled for this maintenance.

In addition, procedure changes have been submitted to require as initial conditions that a mechanic verify proper seating of the packing gland nut prior to performing the applicable tests.

Two additional copies of this letter are enclosed to conform to the original submittal of Reportable Occurrence 76-12, 30-day report.

Very truly yours,


L. D. White, Jr.

5404

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)

8304070610 760525
PDR ADDCK 05000244
S PDR

COPY SENT REGION I