

WESTERN UNION INCOMING

BETH  
008

1974 MAR 11 PM 7 16

USAEC HQS G1WV

ILK4293

WAE172(1745)(1-43723409)DDC2DPD 03/11/74 U.S. ATOMIC ENERGY COMM.  
TWA UNIT

ICS 1P4VE1B RVN

02135 TDVE MORRIS IL 113 03-11 350P COT

~~MRS. J. E. MURPHY~~

DIRECTOR DIRECTORATE OF LICENSING

U.S. ATOMIC ENERGY COMM. HQS

WASH DC 20545

SUBJECT: OPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2

THIS WILL CONFIRM A CONVERSATION WITH MR. F. MAURA OF YOUR  
OFFICE AT 1415 HOURS THIS DATE CONCERNING FAILURE OF THE DRY WELL  
ISOLATION VALVE DURING RUTINE PRIMARY CONTAINMENT ISOLATION

VALVE, AREA 204/04 TO CLOSE DURING RUTINE GUARDEDLY PRIMARY  
CONTAINMENT ISOLATION VALVE SURVEILLANCE. AT THE TIME OF THE OCCURANCE

UNIT 2 WAS IN THE COLD SHUT DOWN CONDITION. HOWEVER, DUE TO  
THE NATURE OF THE FAILURE, A FAULTY SOLENOID OPERATOR FOR THE VALVE,  
PROPER FUNCTIONING OF THE VALVE WOULD HAVE BEEN IMPAIRED DURING  
OPERATION. THIS NOTIFICATION WILL BE FOLLOWED BY A TEN DAY REPORT

W.P. WURDEN, SUPERINTENDENT  
DRESDEN NUCLEAR POWER STATION  
COMMONWEALTH EDISON

RR 1

MORRIS IL

RVN

8304080020 740311  
PDR ADOCK 05000237  
S PDR

COPY SENT REGION



USAEH HQS G1WV

30CP

2047



# Telegram

TELEGRAMS (OTHER THAN MONEY ORDERS)

PHYSICAL DELIVERY required (YES-AGENT, NO-ADDRESSEE)  
AGENT SECTION

VEB246(1743)(1-0372340070) PD 03/11/74 DD740

ICS IPMVEIB NVN

Dr. & Name

3th

942A

312-858-2660

02135 TDVE MORRIS IL 11-03-11 320P CDT

PMS MR JAMES G KEPP attempts to deliver (Indicate DA or BY)

REGIONAL DIRECTOR

DIRECTORATE OF REGULATORY OPERATIONS

REGION 3 WUX

U S ATOMIC ENERGY COMM.

799 ROOSEVELT RD

GLEN ELYN IL 60137

SUBJECT; DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2

THIS WILL CONFIRM A CONVERSATION WITH MR. F. MAURA OF YOUR  
OFFICE AT 1415 HOURS THIS DATE CONCERNING FAILURE OF THE DRY WELL  
EQUIPMENT DRAIN SUMP IN BOARD PRIMARY CONTAINMENT ISOLATION  
VALVE, AO-2001/5, TO CLOSE DURING ROUTINE QUARTERLY PRIMARY  
CONTAINMENT ISOLATION VALVE SURVEILLANCE. AT THE TIME OF THE OCCURANCE



Telegram

REVISION

RE OF MA BY RAN MCI

UNIT 2 WAS IN THE COLD SHUT DOWN CONDITION. HOWEVER, DUE TO THE NATURE OF THE FAILURE, A FAULTY SOLENOID OPERATOR FOR THE VALVE, PROPER FUNCTIONING OF THE VALVE WOULD HAVE BEEN IMPAIRED DURING OPERATION. THIS NOTIFICATION WILL BE FOLLOWED BY A TEN DAY REPORT

W.P. WORDEN, SUPERINTENDENT  
DRESDEN NUCLEAR POWER STATION  
COMMONWEALTH EDISON

1017 NOV 11 6M 8:33

RR 1

MORRIS IL

NNNN

MAR 14 1974



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIRECTORATE OF REGULATORY OPERATIONS  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

TELEPHONE  
(312) 858-2660

*File*

A. RO Inspection Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:  
RO Chief, FS&EB  
RO:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
RO Files

B. RO Inquiry Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:  
RO Chief, FS&EB  
RO:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ  
DR Central Files  
RO Files

C. Incident Notification From: Commonwealth Edison Co. Docket No. 50-237  
(Licensee & Docket No. (or License No.))

Transmittal Date : March 14, 1974

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
Licensing (4)  
DR Central Files  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
RO Files

*Handwritten signature/initials*

8103110777