

USAGM HGS DTN

TLA2801 (49)DE-083

DE JLAIES NL RC PDS MORRIS ILL 7

1971 AUG 6 15 10

DR. PETER A MORRIS DIRECTOR DIVN OF REACTOR LICENSING USAGM

WASNDG 08345

25 AUGUST 1971
1500LT

OPR19 AND 25 DRESDEN NUCLEAR POWER STATION UNITS 2 AND 3

THIS WILL CONFIRM CONVERSATION 1438 THIS DATE WITH E A JORDON
REGARDING AN UNPLANNED LIQUID RELEASE OCCURRING FROM 0945 TO
1105 THIS DATE REPORTABLE UNDER SECTION 66A3 THIS UNPLANNED
RELEASE OCCURED AS A RESULT OF AN ERROR IN VALVE LINE UP CAUSING
B FLOOR DRAIN SAMPLE TANK RELEASE AT A RATE ESTABLISHED FOR
THE A FLOOR DRAIN SAMPLE TANK PRIOR TO ESTABLISHING THE PROPER
DISCHARGE RATE OF THE B TANK. THE RESULTING ACTIVITY IN THE
DISCHARGE WATER WAS 35 PICOCURIES PER LITER OR 35 PERCENT OF
THE ALLOWABLE. A REVIEW OF FACTORS WHICH CONTRIBUTED TO THE
ERROR IS BEING REVIEWED AND ACTION IS BEING TAKEN TO PREVENT
RECCURENCE

151242/Staff 8/16/71
RHE
LK

H K HOYT SUPT DRESDEN NUCLEAR POWER STATION

OPR19 25 2 3 1438 0945 1105 66JA3.7

X-Docket No. 50-249



42007

8304080086 710811
PDR ADOCK 05000237
Q PDR

14022

SACC HGS DTN

COPY SENT REGION

MB

3559