



Commonwealth Edison Company

ONE FIRST NATIONAL PLAZA ★ CHICAGO, ILLINOIS

Address Reply to

POST OFFICE BOX 767 ★ CHICAGO, ILLINOIS 60690

May 14, 1971

Dr. Peter A. Morris, Director
Division of Reactor Licensing
U.S. Atomic Energy Commission
Washington, D.C. 20545

Subject: Additional Information concerning the
operation of Dresden Unit 2

Dear Dr. Morris:

On March 22, 1971, we submitted to you nine reports concerning several operational problems on Dresden Unit 2. On April 14, at a meeting with your Staff, we discussed these reports. At that meeting, members of your Staff requested additional information concerning the jet pump riser brace vibration problem, the venting problem as it related to the installation of a new air system for the main steam line isolation valves, core asymmetry, and radwaste. On April 24, 1971, we submitted to you four special reports which were also concerned with operational problems encountered on Dresden Unit 2.

Enclosed is the supplementary information which your Staff requested in our meeting of April 14. In addition, we are submitting additional information concerning the resolution of the limitorque problem and the core spray water hammer problem which was discussed in Report Nos. 11 and 13, respectively.

We would like to point out again that the report concerning off-gas emissions will be filed with you prior to June 1, 1971, and that the fuel report which discusses the cause of failed fuel at Dresden Unit 2 will also be submitted by June 1.

*1345 PR/Staff 7/27/71
748*

*enclosures in operations
50-237*

8304080259 710514
PDR ADOCK 05000237
P PDR

incident
2343
111
COPY SENT REGION