

USAEC HQS GTNN

WU WSH

WESTERN UNION INCOMING

TLXB105 (43)DEA276

DE JLA194 BS NL PDF MORRIS ILL 15

DR PETER A MORRIS, DIRECTOR

DIVISION OF REACTOR LIS.

20045

US ATOMIC ENERGY COMMISSION WASH DC

THIS IS TO INFORM YOU OF A WIRING ERROR DISCOVERED ON APRIL 4TH 1971 THAT RESULTED IN A PHASE REVERSAL ON THE BACK-UP POWER SUPPLY TO THE REACTOR INJECTION VALVE OF THE LOW PRESSURE COLLANT INJECTION SYSTEM. THIS WOULD HAVE PREVENTED THE SYSTEM FROM OPERATING AS DESIGNED WHEN ON BACK-UP POWER. THE WIRING ERROR WAS CORRECTED IMMEDIATELY. A TEN DAY REPORT AS REQUIRED UNDER SECTION 6.6.3.2 OF THE DPR19 IER. SPECS. IS BEING PREPARED. AS DISCUSSED ON APRIL 14, 1971 WITH G. FIORELLI OF REGION 3 COMPLIANCE AND ON APRIL 15, 1971 WITH R. TEDESCO OF DRL A REQUEST IS HEREBY MADE FOR A 7 DAY EXTENTION TO THIS REPORTING REQUIREMENT.

H K HOYT SUPT DRESDEN NUCLEAR POWER STATION.

ATH 1971 6.6.3.2 DPR19 14 1971 3 15 1971 DRL 7.

ENDP EST

WU WSH+

WESTERN UNION INCOMING

USAEC HQS GTNN

1304

13/CR/Staff 5/6/71
RAE
GBA
LX
DP

8304080324 710416
PDR ADUCK 05000237
S PDR

COPY SENT REGION