



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

Files

A. RO Inspection Report No. _____

Transmittal Date : _____

Distribution:

RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
RO Files

Distribution:

RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files
RO Files

B. RO Inquiry Report No. _____

Transmittal Date : _____

Distribution:

RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
RO Files

Distribution:

RO Chief, FS&EB
RO:HQ
DR Central Files
RO Files

C. Incident Notification From: Commonwealth Edison Co., Docket No. 50-237
(Licensee & Docket No. (or License No.))

Transmittal Date : November 30, 1973

Distribution:

RO Chief, FS&EB
RO:HQ (4)
Licensing (4)
DR Central Files
RO Files

Distribution:

RO chief, FS&EB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files
RO Files

8304080380 731123
PDR ADOCK 05000237
S PDR



western union

Telegram

RECEIVED

NOV 28 4 10 PM '73

NOVEMBER 23 FOR A MECHANICAL MAINTENANCE TO STOP STEAM LEAK
ON TURBINE STOP VALVES WHICH WAS SOURCE OF MOISTURE

W P WORDEN SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON CO RRI MORRIS ILLINOIS

NNNN

TELEGRAMS (OTHER THAN MONEY ORDERS)

Is PHYSICAL DELIVERY requested? (YES-AGENT NO-ADDRESSEE)

AGENT SECTION

ADDRESSEE SECTION

Nbr. & name

Nbr.

Date dtd 11/26

Date dtd 10/5/73

To

To be mailed or filed

mail

PS

By

Attempts to deliver (indicate DA or BX)

Def 430pm Def 530pm da 928p
da 11-24-226Am. 435Am.

NOV 28 1973



~~URGENT~~
Telegram

1973 NOV 23 PM 3: 05

VED127(1605)(1-017751C327)PD 11/23/73 1603

ICS IPMVEIC MVN

03147 TDVEMORRIS ILL 121 11-23 1252P CST

PMS JAMES G KEPPLER REGIONAL DIR DIRECTORATE REGULATORY OPERATIONS
REGION 3 WUX US ATOMIC ENERGY COMM 799 ROOSEVELT RD
GLENELLYN ILL 60137

SUBJECT DPR19 DRESDEN NUCLEAR POWER STATION UNIT 2.

THIS WILL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE
AT 1145 HOURS THIS DATE CONCERNING HPCI INOPERABLE. APPROXIMATELY
2000 NOV 22, 1973 OPERATIONS TRACED 250 VDC AND 125 VDC ROUNDS TO
HPCI AUXILLARY OIL PUMP WHICH PROVIDES LUBRICATION AND CONTROL OIL
FOR HIGH PRESSURE COOLANT INJECTION TURBINE. DECLARED SYSTEM
INOPERABLE, PROFORMED REQUIRED SURVELLIENCE AND CALLED
ELECTION TO CLEA GROUND. ELECTRICIAN FOUND MOISTURE HAD
ACCUMULATED IN JUCTION BOX AND HE CLEARED GROUND BY DARINING
WATER OUT. PLACED HPCI OUT OF SERVICE ABOUT 0830

Handwritten: 00120
Handwritten: 50237

WESTERN UNION INCOMING

Beth
008

50-237

1973 NOV 23 PM 4 37

USAEC HQS GTWN

WU WSH

TLXA098 WAF104(1545)(1-016890C327)PD 11/23/73 1543

ICS IPMVEIC MVN

U.S. ATOMIC ENERGY COMM.
TWX UNIT

03137 TDVE MORRIS IL 121 11-23 1251P CST

PMS J F OLEARY DIR DIRECTORATE OF LICENSEING US ATOMIC ENERGY COMM

WUS WASHDC

SUBJECT DPRI9 DRESDEN NUCLEAR POWER STATION UNIT 2

THIS WILL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE AT 1145 HOURS THIS DATE CONCERNING HPCI INOPERABLE. APPROXIMATELY 2000 NOV 22, 1973 OPERATIONS TRACED 250 VDC AND 125 VDC ROUNDS TO HPCI AUXILLARY OIL PUMP WHICH PROVIDES LUBRICATION AND CONTROL OIL FOR HIGH PRESSURE COOLANT INJECTION TURBINE. DECLARED SYSTEM INOPERABLE PROFORMED REQUIRED SURVEILIENCE AND CALLED ELECTRICIAN TO CLEAR GROUND. ELECTRICIAN FOUND MOISTURE HAD ACCUMULATED IN JUNCTION BOX AND HE CLEARED GROUND BY DRAINING WATER OUT/PLACED HPCI OUT OF SERVICE ABOUT 0830 NOVEMBER 23 FOR A MECHANICAL MAINTENANCE TO STOP STEAM LEAK ON TURBINE STOP VALVES WHICH WAS SOURCE OF MOISTURE.

W P WORDEN SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON CO RRI MORRIS ILLINOIS

NNNN

425PEST

USAEC HQS GTWN



Handwritten: 50237

8103120674

8:15
COPY SENT REGION