



Telegram

1974 JUL 11 PM 4:59

VEE302(1751)(1-040760C162)PD 06/11/74 1748

ICS IPMVEIB MVN

02214 TDVE MORRIS IL 127 06-11 254P CDT
PMS JAMES G KEPPLER REGIONAL DIRECTOR
DIRECTORATE OF REGULATORY OPERATIONS REGION 3
US ATOMIC ENERGY COMM 799 ROOSEVELT RD
GLEN ELLYN IL 60137

SUBJECT EPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2.
THIS WILL CONFIRM A CONVERSATION WITH F MAURA OF YOUR OFFICE
AT 1045 HOURS THIS DATE CONCERNING INSPECTION BERGAN-PATTERSON
HYDROIC TYPING RESTRAINTS WITH IN THE DRY WELL. DURING THIS
INSPECTION 8 OF THE 31 RESTRAINTS EXAMINED WERE FOUND TO BE
DEFECTIVE. 7 OF THESE 8 WERE DEFECTIVE DUE TO LOSS OF HYDROIC
FLUID WHILE THE LAST WAS INOPERABLE DUE TO WHAT APPEARS AS
VIBRATION OF A CLEANUP SYSTEM HEADER WITHIN THE DRY WELL CASING

*hault
5022*

8304080445 750228
PDR ADDCK 05000237
PDR



Telegram

1974 JUN 11 PM 4:59

THE BOLTS ON THE RESTRAINT TO BACK OUT OF THE PIPING BRACKETS.
REPAIRS ARE BEING INITIATED ON THE 8 RESTRAINTS AND WILL BE
REPORTED TO YOU WITHIN 10 DAYS OF THIS NOTIFICATION

BB STEPHENSON
SUPERINTENDENT
DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON COMPANY
RR 1
MORRIS ILLINOIS 60450

TELEGRAMS (OTHER THAN MONEY ORDERS)
PHYSICAL DELIVERY requested? (YES-AGENT, NO-ADDRESSEE)
AGENT SECTION
Nbr. & Name 412 Time dld 1025H To 312-858-8060
Date dld 4/12 by MA
To be mailed or filed MA
Attempts to deliver (Indicate DA or BY)

NNNN JUN 13 1974