

BETH  
OOF

# WESTERN UNION INCOMING

S+  
USAEC HQS GTWN  
WU WSH  
TLXB064 WAG268(1751)(1-040760C162002)PD 06/11/74 1748

ICS IPMVEIB MVN

02215 TDVE MORRIS IL 127 06-11 254P CDT  
PMS J F OLEARY WUX DIRECTOR DIRECTORATE OF LICENSING  
US ATOMIC ENERGY COMM  
WASHINGTON DC 20545

SUBJECT EPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2.  
THIS WILL CONFIRM A CONVERSATION WITH F MAURA OF YOUR OFFICE  
AT 1045 HOURS THIS DATE CONCERNING INSPECTION BERGAN-PATTERSON  
HYDROLIC TYPING RESTRAINTS WITH IN THE DRY WELL. DURING THIS  
INSPECTION 8 OF THE 31 RESTRAINTS EXAMINED WERE FOUND TO BE  
DEFECTIVE. 7 OF THESE 8 WERE DEFECTIVE DUE TO LOSS OF HYDROLIC  
FLUID WHILE THE LAST WAS INOPERABLE DUE TO WHAT APPEARS AS  
VIBRATION OF A CLEANUP SYSTEM HEADER WITHIN THE DRY WELL CASUING  
THE BOLTS ON THE RESTRAINT TO BACK OUT OF THE PIPING BRACKETS.  
REPAIRS ARE BEING INITIATED ON THE 8 RESTRAINTS AND WILL BE  
REPORTED TO YOU WITHIN 10 DAYS OF THIS NOTIFICATION

BB STEPHENSON

SUPERINTENDENT

DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON COMPANY

RR1

MORRIS ILLINOIS 60450

718P EDT

USAEC HQS GTWN



U.S. ATOMIC ENERGY COMM.  
TWX UNIT

1974 JUN 11 PM 8 32

WESTERN UNION INCOMING

5245

8304080448 750228  
PDR ADOCK 05000237  
Q PDR

COPY SENT REGION