

WESTERN UNION INCOMING



1974 FEB 14 PM 12 34

U.S. ATOMIC ENERGY COMM.  
TWX UNIT

*Best  
008*

4\*  
USAEC HQS GTWN

\*  
USAEC HQS GTWN  
WU WSH+  
USAEC HQS GTWN

TLX267 WAC292(2128)(1-847755C044)PD 02/13/74 2125

IGS IPWVETB NVN

02329 TDOE MORRIS IL 102 02-13 346P CDT  
MRS MR. J F O'LEARY

DIRECTOR

DIRECTORATE OF LICENSING

US ATOMIC ENERGY COMMISSION

WUX

WASHDC 20545

SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2.

THIS WILL CONFIRM A CONVERSATION WITH F. MAURA OF YOUR OFFICE  
AT 1030 HOURS THIS DATE CONCERNING INSPECTION OF BERGEN-  
PATTERSON HYDRAULIC PIPING RESTRAINT WITHIN THE DRY WELL  
DURING THE CURRENT PLANT OUTAGE AS NOTIFIED TO YOU ON  
2-11-74. DURING THIS INSPECTION 12 OF THE 31 RESTRAINTS  
WITHIN THE DRY WELL WERE FOUND TO BE DEFECTIVE DUE TO THE

LOSS OF HYDRAULIC FLUID. A PROGRAM IS BEING INITIATED TO  
OVERHAUL THESE 12 RESTRAINTS AND WILL BE RECORDED TO YOU  
IN A FOLLOWING 10-DAY NOTIFICATION

W P WORDEN SUPERINTENDENT DRESDEN NUCLEAR  
POWER STATION COMMONWEALTH EDISON COMPANY RURAL ROUTE 1 MORRIS IL  
1105A EDT

WU WSH+

USAEC HQS GTWN

WESTERN UNION INCOMING

8304080455 750228  
PDR ADOCK 05000237  
Q PDR

1239

COPY SENT REGION