



Commonwealth Edison

One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

BBS Ltr. #458-75

Dresden Nuclear Power Station
R. R. #1
Morris, Illinois 60450
July 28, 1975

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operation-Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137


SUBJECT: CORRECTION OF REPORT NUMBERS FOR LETTERS #229-75 AND #323-75
FROM B. B. STEPHENSON

References: 1) Letter #229-75 dated April 3, 1975
2) Letter #323-75 dated May 23, 1975

Letter #229-75 dated April 3, 1975 (Thermal trip of MC-3-1501-5A) was not assigned a report number. The correct report number for this unusual event is 50-249/1975-12. Reference 3 for letter #229-75 should include only these incident report numbers: 50-249/1975-18, 50-249/1975-11, and 50-249/1975-10.

The incident report number for letter #323-75 dated May 23, 1975 (Roll of Nashua tape lost in Unit-2 reactor) was incorrectly designated as 50-237/1975-44. The correct report number for this incident is 50-237/1975-25.

Sincerely,


B. B. Stephenson
Superintendent

BBS:TJK:smp

File/NRC

8304110116 750728
PDR ADCK 05000237
S PDR

AUG

09405

COPY SENT REGION