

March 25, 1974

Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 4
DOCKET NO. 50-251
REINSPECTION OF HYDRAULIC PIPE RESTRAINTS

Reinspection of the safety related hydraulic pipe restraints that are accessible during power operation was completed on March 12, 1974, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The inspection revealed that all of the restraints were operable. There were seven restraints inspected and all are of the Bergen-Paterson design.

Very truly yours,

J. A. De Mastis
for

R. E. Uhrig
Director of Nuclear Affairs

REU/HNP/kmw

cc: Mr. Norman C. Moseley
Mr. Jack R. Newman



*Received
50-251
(RAB 934)*