



FLORIDA POWER & LIGHT

March 1, 1974

Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545



Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 3
DOCKET NUMBER 50-250
REINSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS ACCESSIBLE
DURING POWER OPERATION

Reinspection of the accessible safety related piping restraints in accordance with the continuing requirements of the Directorate of Licensing letter of November 8, 1973, was completed on February 18, 1974. There were 14 restraints inspected and all are of the Bergen-Paterson design. The inspection showed that all of these restraints were in satisfactory condition.

Very truly yours,

R. E. Uhrig
Director of Nuclear Affairs

HNP/kmw

cc: Mr. Norman C. Moseley
Mr. Jack R. Newman

8304110225 741024
PDR ADOCK 05000251
Q PDR

COPY SENT REGION

HELPING BUILD FLORIDA

2223

Handwritten:
50-250
(Rob 2-4)