

FLORIDA POWER & LIGHT COMPANY

February 21, 1974

Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 30545

Dear Mr. Giambusso:


TURKEY POINT UNIT NO. 4
DOCKET NO. 50-251
INSPECTION OF SAFETY RELATED HYDRAULIC
PIPE RESTRAINTS



Inspection of the safety related pipe restraints that are accessible during power operation was conducted on February 8, 1974. The inspection was in accordance with the continuing requirements of the Atomic Energy Commission Directorate of Licensing letter of November 8, 1973.

All of the restraints inspected were found to be operable. The inspection included a total of seven restraints all of which were of the Bergen-Paterson design.


Very truly yours,


R. E. Uhrig
Director of Nuclear Affairs

HNP/REU/kmw

cc: Mr. Norman C. Moseley, Director Region II
Mr. Jack R. Newman

8304110230 741024
PDR ADOCK 05000251
Q PDR


1628