



Telegram

VEE316(2224)(1-036616C158)PD 06/07/73 2222 1973 JUN -7 PM10:26

ICS IPMVEIG MVN

07193 NL TDVE MORRIS IL 107 06-07 408PM CDT (OTHER THAN MONEY ORDERS)

PMS BOYCE GRIER

DIRECTOR DIVISION OF COMPLIANCE

REGION 3 US ATOMIC ENERGY COMMISSION

799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT DPR19 DRESDEN NUCLEAR POWER STATION UNIT 2.

THIS WILL CONFIRM A CONVERSATION WITH MR MAURA

OF YOUR OFFICE AT 1515 HOURS THIS DATE CONCERNING

ISOLATION CONDENSOR MOTOR OPERATED VALVE 2-1301-1

WHICH WAS FOUND WITH THERMAL OVERLOADS TRIPPED. VALVE

WAS IN ITS NORMAL OPEN POSITION SO ISOLATION CONDENSOR MOTOR

FUNCTION WAS NOT EFFECTIVE. VALVE ISOLATE ON HIGH

STEAM FLOW IN THE ISOLATION CONDENSOR AND THIS

SF-1201 (RS-69)

FUNCTION WAS NOT AVAILABLE. LAST SUCCESSFUL SURVEILLANCE
WAS MAY 14, 1973. ALL INDICATIONS WAS NORMAL FOR VALVE.
THERMAL OVERLOAD WERE SET FOR MANUAL INSTEAD OF AUTOMATIC
BUT CAUSE OF TRIP STILL UNDER INVESTIGATION.

W P WORDEN SUPERINTENDANT

DRESDON NUCLEAR POWER STATION

COMMONWEALTH EDDISON CO

RURAL ROUTE 1

MORRIS IL

50-237
inquiring

JUN 11 1973

8304120016 730607
PDR ADOCK 05000237
S PDR