



Commonwealth Edison Company

ONE FIRST NATIONAL PLAZA ★ CHICAGO, ILLINOIS

Address Reply to:

POST OFFICE BOX 767 ★ CHICAGO, ILLINOIS 60690

Dresden Nuclear Power Station
R. R. #1
Morris, Illinois 60450

February 18, 1971



Dr. Peter A. Morris, Director
Division of Reactor Licensing
U.S. Atomic Energy Commission
Washington, D.C. 20545

Dr. Morris:

Reference: Our letter of January 12, 1971,
regarding License DPR-19, Dresden Nuclear Power Station,
Unit #2 Section 6.6.C.1 of Technical Specifications.

Please revise the second paragraph, Problem and Initial Action, to read as follows: "At 3:00 p.m. on January 5, 1971, a surveillance test of the Standby Gas Treatment System was conducted. Initial configuration was with "A" train in "Primary" and "B" train in "Standby". To start the test, the ventilation radiation monitors were tripped. "A" train, which was in "Primary", auto started and "B" train remained in "Standby". At this time it was noticed that "A" train had no discharge damper position indication. Investigation of the damper motor breaker indicated that it was tripped and could not be reset."

IS/OR/Staff 3/4/71
RAE
LK
DP

H. K. Hoyt
H. K. Hoyt
Superintendent

HKH:LDB:dmc

8304120129 710218
PDR ADOCK 05000237
S PDR

COPY SENT REGION

11665

824