



November 13, 1975

L-75-546

Director of Nuclear Reactor Regulation  
Attn: Mr. Roger Boyd, Acting Director  
Division of Reactor Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Boyd:

**TURKEY POINT UNIT 3  
DOCKET NO. 50-250  
INSPECTION OF SAFETY RELATED  
HYDRAULIC PIPE RESTRAINTS  
LOCATED OUTSIDE CONTAINMENT**

**TE FILE COPY**

The subject inspection was completed on November 3, 1975, in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973.

All safety related hydraulic pipe restraints located outside containment were in satisfactory condition.

Very truly yours,

*J. A. De Mastry*  
for.

Robert E. Uhrig  
Vice President

REU/MAS/cpc

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire

**COPY SENT REGION**

*[Handwritten signature]*

8304120244 751217  
PDR ADDCK 05000251  
Q PDR

**13156**