

LICENSEE EVENT REPORT

CONTROL BLOCK 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 M Y I E S 2 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

CATEGORY 01 CON 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION

02 7 8 9 During normal operation, with No. 23 charging pump inoperable, a leak
03 7 8 9 developed at the No. 2 high pressure head cylinder gasket of Pump No. 21,
04 7 8 9 The remaining pump was operable. No. 21 pump was removed from service
05 7 8 9 for replacement of the head gasket. The pump was returned to service
06 7 8 9 within the 24 hr. period permitted by the Technical Specifications. (Cont'd)

SYSTEM CODE 07 8 9 10 CAUSE CODE 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

CAUSE DESCRIPTION

08 7 8 9 This type GX-300 Quintuplex, variable speed positive displacement
09 7 8 9 pump became inoperable due to a leaking head gasket. Design modifi
10 7 8 9 cations are being investigated.

FACILITY STATUS 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL EXPOSURES
13 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PROBABLE CONSEQUENCES
15 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ADDITIONAL FACTORS
18 7 8 9 Event Description (CONT'D)-Similar events occurred
19 7 8 9 on November 5, August 29, August 27, and July 22, 1975. [A.O.75-2-27(B)]

NAME: Michael Shatkouski

PHONE: (914)-739-8823

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 469-3819

December 31, 1975

Re Indian Point Unit No. 2
Docket No. 50-247
A.O.-75-2-27(B)

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406



Dear Mr. O'Reilly

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-26, the attached report of Abnormal Occurrence A.O.-75-2-27(B) is submitted. This report fulfills the requirement for a written report within 30 days of an Abnormal Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 3.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours

William J. Cahill, Jr.
William J. Cahill, Jr.
Vice President

Enc.
mrh

Copy to Director of Nuclear Reactor Regulation
ATTN: Mr. Donald F. Knuth, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William F. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555