

921

LAW OFFICES OF
BISHOP, LIBERMAN, COOK, PURCELL & REYNOLDS
1200 SEVENTEENTH STREET, N.W.
WASHINGTON, D.C. 20036
(202) 857-9800
TELEX 440574 INTLAW U

DOCKETED
USNRC

IN NEW YORK

84-APR-30 12:28
NEW YORK NEW YORK 10004

OFFICE 212 444-6900
DOCKETING & SERVICE
BRANCH

April 27, 1984

Peter B. Bloch, Esquire
Atomic Safety and
Licensing Board
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Dr. Walter H. Jordan
881 West Outer Drive
Oak Ridge, Tennessee

Dr. Kenneth A. McCollom, Dean
Division of Engineering,
Architecture & Technology
Oklahoma State University
Stillwater, Oklahoma 74078

Subj: Texas Utilities Electric Company, et al.
(Comanche Peak Steam Electric Station,
Units 1 and 2), Docket Nos. 50-445 and 50-446 *CL*

Gentlemen:

In accordance with the Licensing Board Chairman's request (Tr. 11784-7), the attached affidavit of W.E. Baker and C.T. Brandt provides a report on the required documentation regarding F.E. Coleman's welding of misdrilled holes in the Unit 1 cable spreading room. As indicated in the affidavit, Applicants determined that (1) the welding of misdrilled holes by Mr. Coleman in the Unit 1 cable spreading room was not in conflict with applicable procedures, the pertinent welding code (AWS D1.1), or engineering instructions and (2) documentation reflects that QC inspections of such welds were being performed.

Sincerely,

M. H. Philips, Jr.
Malcolm H. Philips, Jr.
Counsel for Applicants

cc: Service List

8405020082 840427
PDR ADOCK 05000445
G PDR

DS03