



Telegram

VEA216(1649)(2-032643E041)PD 02/10/75 1649

ICS IPMBNGZ CSP

8159424449 TDBN MORRIS IL 89 02 10 0449

PMS JAMES G KEPPLER, REGIONAL DIRECTOR, WUX TO DELIVER:

DIRECTORATE OF REGULATORY OPERATIONS REGION 3 U.S. ATOMIC ENERGY

COMMISSION 799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT: DPR-19, DRESDEN NUCLEAR POWER STATION UNIT II.

THIS WILL CONFIRM THE CONVERSATION WITH MR JOHNSON OF YOUR OFFICE AT 1300 HOURS THIS DATE CONCERNING ADDITIONAL PIPE CRACK FOUND BY ULTRA-SONIC TEST ON CORE SPRAY LOOP A IN THE SECTION OF PIPE DOWN STREAM OF THE MANUEL VALVE IN THE DRYWELL. THE CRACK IS IN WELD 10-25 AT 12 OCLOCK AND IS APPROXIMATELY .3 INCHES LONG. THIS WILL BE CORRECTED WHEN OTHER CORE SPRAY PIPING IS REPLACED LATER THIS MONTH.

B B STEPHENS SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

COMMON WEALTH EDISON CO RRI MORRIS IL 60450

(RS-69)

8304140523 750407
PDR ADDCK 05000237
PDR

FEB 13 1975